

Example Picture #12
Pheasant Run
6100 N. Meridian, OKC
Terminal 6106B
05-20-03



Terminal door cannot be closed properly due to placement of Cox's 4 pair wire.



Example Picture #13
Pheasant Run
6100 N. Meridian, OKC
Terminal 6112B
05-21-03

SBC OK


Picture
24

Terminal door cannot be closed properly due to placement of Cox's 4 pair wire.

Example Picture #14
Woodscape I
4401 NW 39th, OKC
Terminal 4401-3
05-22-03

Cox removed 4 NTWs
from SBC terminal.

Close up of grommet
pulled from terminal when
Cox removed NTWs.



Cox

Example Picture #15
Forest Pointe
11525 N. Meridian, OKC
Terminal P
07-28-03


Cox removed NTWs
from SBC terminal
leaving excessive
wire leads.

SBC OK

Cox removed 5 NTWs
from SBC terminal.

Protective P-Guard in the
back of terminal broken to
place NTWs in Cox box.

Picture
↑↑



Wasps entered SBC terminal through hole left by Cox and/or through terminal door not being closed properly. Wasp nest was found inside of terminal.


SBC OK

Cox

Knockout removed and not sealed. Cox has the only wires going through knockout.

Internal splice.

Example Picture #16
Market at Paseo
600 NW 29th, OKC
Terminal 1
07-15-03



Example Picture #17
The Gables
12901 N. MacArthur, OKC
Terminal 9
06-03-03

Cox

Internal splice.

SBC OK

Cox removed NTWs from SBC terminal leaving excessive wire leads.

Plug material has been removed.

Protective P-Guard has been broken and NTWs removed.

Broken P-Guard on ground.

