
Cox
Example Picture #6
Pheasant Run
6100 N. Meridian, OKC
Terminal 6118B
05-21-03
Picture
29
Knockout removed and not sealed. Terminal block shows moisture damage. Cox has the only wire going through knockout. All NTWs enter through grommet in the back of SBC's terminal.
SBC OK
Inside terminal door not properly closed.


Cox
Example Picture #7
Raindance
2201 NW 122, OKC
Terminal 27 East
07-10-03
SBC OK
Picture
Excessive wire ends.
Cox's 4 pair wire.
Cox's splice box.
Cox removed 4 NTWs
from SBC terminal.
Plug material has been removed.


Cox
Example Picture #8
Pheasant Run
6100 N. Meridian, OKC
Terminal 6106A
05-20-03
SBC OK
Close up of hole drilled in side of terminal.
Cox drilled hole in side of SBC's terminal to gain access to NTWs.
Internal splice.

Example Picture #9
The Boardwalk
6400 NW Expressway
Terminal 9A
09-16-03





Example Picture #10
The Boardwalk
6400 NW Expressway
Building 8 - Terminal 8B
09-16-03


Example Picture #11
Raindance
2201 NW 122nd, OKC
Terminal 18B
07-10-03
Cox
NTWs and Cox's 4 pair placed in SBC terminal.
SBC OK
Cox's splice box.
Picture 2
Splice is exposed to the elements.
Internal splice.