
Example Picture #12
Pheasant Run
6100 N. Meridian, OKC
Terminal 6106B
05-20-03
Cox
SBC OK
Terminal door cannot be closed properly due to placement of Cox's 4 pair wire.


Example Picture #13
Pheasant Run
6100 N. Meridian, OKC
Terminal 6112B
05-21-03
Cox
SBC OK
24
Terminal door cannot be closed properly due to placement of Cox's 4 pair wire.


Example Picture #14
Woodscape I
4401 NW 39th, OKC
Terminal 4401-3
05-22-03
Cox removed 4 NTWs from SBC terminal.
Cox
SBC OK
Close up of grommet pulled from terminal when Cox removed NTWs.
Picture 2


Cox
Example Picture #15
Forest Pointe
11525 N. Meridian, OKC
Terminal P
07-28-03
Cox removed NTWs from SBC terminal leaving excessive wire leads.
SBC OK
Cox removed 5 NTWs from SBC terminal.
Protective P-Guard in the back of terminal broken to place NTWs in Cox box.
Picture 11


Wasps entered SBC terminal through hole left by Cox and/or through terminal door not being closed properly. Wasp nest was found inside of terminal.
Cox
SBC OK
Knockout removed and not sealed. Cox has the only wires going through knockout.
Internal splice.
Example Picture #16
Market at Paseo
600 NW 29th, OKC
Terminal 1
07-15-03


Example Picture #17
The Gables
12901 N. MacArthur, OKC
Terminal 9
06-03-03
Cox
Internal splice.
SBC OK
Cox removed NTWs from SBC terminal leaving excessive wire leads.
Protective P-Guard has been broken and NTWs removed.
Plug material has been removed .
Broken P-Guard on ground.