



Victoria Carter-Hall
Manager - Federal Regulatory

AT&T Services, Inc.
1120 20th Street, NW
10th Floor
Washington, DC 20036
202.457.2164
Email: vc3624@att.com

AMENDMENT

October 21, 2016

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 12th Street, SW
Washington, DC 20554

**Re: Certification of Public Notice of Network Change under Rule 51.329(a)
CC Docket No. 96-98**

Dear Ms. Dortch:

Pursuant to the notification of requirements in §51.325 -- §51.335 of the Commission's rules, AT&T hereby submits this certification of Public Notice of Network Change. A description of the network change is attached, and also available online. The attached notification was originally filed on September 16, 2016 (ATT20160913L.2) and is being amended to update a typographical error under the Network Change explanation.

<u>NUMBER</u>	<u>NETWORK CHANGE</u>	<u>LOCATION OF CHANGE</u>
ATT20160913L.2	This is a revision to the short term network change notice ATT20150911S.2 rev2 . The reason for this revision is the due date is not obtainable due to network freezes and AT&T is extending the window of implementation to on or after 2 nd quarter 2017 to meet these ASR/LSR obligations for carrier rehomings. AT&T Southwest has developed a project with the plan to eliminate the Nortel DMS STPs in Longview/Tyler, Texas. This will require re-homing all the SS7 linksets from the Longview/Tyler Nortel DMS STPs (LGVWTXPL01W/TYLRTXLY03W) into the Dallas/Fort Worth, Texas (DLLSTXTA38W/FTWOTXED36W) Tekelec STPs. This change will consolidate STPs in LATA (554) to LATA (552).	Longview/Tyler, TX Dallas/Ft. Worth, TX

This notice is available at: <https://ebiznet.att.com/networkreg/>

Should you have any questions, please do not hesitate to contact me at 202.457.2164.

Sincerely,

Victoria Carter-Hall

Attachment

cc: Michele Berlove
Carmell Weathers

PUBLIC NOTICE of NETWORK CHANGE UNDER RULE 51.329(a)

Network Disclosure Number: ATT20160913L.2 Issue Date: 09/16/2016
 Modification Date: On or After 2nd Qtr 2017

Carrier's Name: AT&T Southwest

Carrier's Address: 2800 W 10th St. Sioux Falls, SD 57104

Contact: Your Account Manager or Service Representative
Technical Issues
 Terry McKenzie
 2800 W 10th St.
 Sioux Falls, SD 57014
 605-530-9456
tm921b@att.com

Public Notice: **can be obtained on the Internet at:**
<https://ebiznet.att.com/networkreg/>

Network Change:

This is a revision to the short term network change notice **ATT20150911S.2 rev2**. The reason for this revision is the due date is not obtainable due to network freezes and AT&T is extending the window of implementation to on or after 2nd quarter 2017 to meet these ASR/LSR obligations for carrier rehomng. **AT&T Southwest** has developed a project with the plan to eliminate the Nortel DMS STPs in Longview/Tyler, Texas. This will require re-homing all the SS7 linksets from the Longview/Tyler Nortel DMS STPs (**LGVWTXPL01W/TYLRTXLY03W**) into the Dallas/Fort Worth, Texas (**DLLSTXTA38W/FTWOTXED36W**) Tekelec STPs. This change will consolidate STPs in LATA (554) to LATA (552).

Description of Type of Changes Planned:

AT&T Southwest will be decommissioning the STPs in the AT&T Longview/Tyler, TX area. Carriers who connect with AT&T in the Longview/Tyler LATA (554) need to migrate their SS7 linksets. The NEW FSPOI codes are (**LGVWTXPL0JW/TYLRTXLY0MW**). AT&T will transport the SS7 links from the FSPOI to the new STP location in LATA 552.

Longview/Taylor- LATA-554

LGVWTXPL01W / TYLRTXLY03W

Point Code - 249-039-000 / 249-038-000---Alias 249-087-000

Dallas/Fort Worth-LATA-552

DLLSTXTA38W / FTWOTXED36W

Point Code - 249-030-000 / 249-031-000--Alias 249-096-000

Description of Reasonably Foreseeable Impact of the Planned Changes:

Carriers will need to move their SS7 links and must coordinate the activity with AT&T. AT&T will communicate more details with affected Carriers in 2nd Quarter 2016. It is anticipated that Carriers will have to issue ASRs to connect to the FSPOI in the existing LATA (562) and that **Carriers will not have to transport their SS7 links any further than they presently do.** ASRs will need to be issued prior to the cutovers with the existing FSPOI, and the new Far End CLLI and Point Code. The Carriers will need a technician in their Central Office or STP during the maintenance window on the night of the cutover to make changes in the SS7 routing tables with the new set of point codes shown above. Acknowledgement of this disclosure (ASR/LSRs) and *intent* for traffic is requested by **12/1/16**.

Location of Change:

CLLI Code/Statewide	City	State	Implementation Date
LGVWTXPL01W / TYLRTXLY03W	Longview/Tyler	Texas	On or After 2 nd Qtr 2017
To	Dallas/Ft. Worth	Texas	On or After 2 nd Qtr 2017
DLLSTXTA38W / FTWOTXED36W			