



Victoria Carter-Hall  
Manager - Federal Regulatory

AT&T Services, Inc.  
1120 20<sup>th</sup> Street, NW  
10<sup>th</sup> Floor  
Washington, DC 20036  
202.457.2164  
Email: [vc3624@att.com](mailto:vc3624@att.com)

September 16, 2016

Ms. Marlene H. Dortch, Secretary  
Federal Communications Commission  
445 12<sup>th</sup> Street, S.W.  
Washington, DC 20554

**Re: Certification of Public Notice of Network Change under Rule 51.329(a)  
CC Docket No. 96-98**

Dear Ms. Dortch:

Pursuant to the notification requirements in §51.325 -- §51.335 of the Commission's rules, AT&T hereby submits this certification of Public Notice of Network Change. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
ATT20160913L.2	<p>AT&amp;T Southwest will be decommissioning the STPs in the AT&amp;T Longview/Tyler, TX area. Carriers who connect with AT&amp;T in the Longview/Tyler LATA (554) need to migrate their SS7 linksets. The NEW FSPOI codes are <b>(LGVWTXPL0JW/TYLRTXLY0MW)</b>. AT&amp;T will transport the SS7 links from the FSPOI to the new STP location in LATA 552.</p> <p><b>Longview/Taylor- LATA-554</b> LGVWTXPL01W / TYLRTXLY03W Point Code - 249-039-000 / 249-038-000---Alias 249-087-000</p> <p><b>Dallas/Fort Worth-LATA-552</b> DLLSTXTA38W / FTWOTXED36W</p> <p>Point Code - 249-030-000 / 249-031-000--Alias 249-096-000</p>	<p><b>Longview/Tyler, TX</b></p> <p><b>Dallas/Ft. Worth, TX</b></p>

Ms. Marlene H. Dortch, Secretary

Page 2

September 16, 2016

This notice is also available at: <https://ebiznet.att.com/networkreg/>

If you have any questions, please do not hesitate to contact me at (202) 457-2164.

Sincerely,

A handwritten signature in black ink that reads "Victoria Carter-Hall". The signature is written in a cursive style and is placed on a light gray rectangular background.

Victoria Carter-Hall

Attachments

cc: Carmell Weathers

**CERTIFICATION OF PUBLIC NOTICE(s) OF NETWORK  
CHANGE(s) UNDER RULE 51.329(a)**

On **September 16, 2016** the following Public Notice(s) of Network Change(s) have been made by **AT&T Southwest** Pursuant to Code of Federal Regulations 47, Subsections 51.325 – 51.335.



Terry L McKenzie  
Manager - Regulatory Relations  
Telephone: (605) 530-9456      Date: 09/16/2016

The Public Notice(s) can also be obtained on the Internet at:

<https://ebiznet.att.com/networkreg/>

**Title(s) of Network Notification(s):**

**ATT20160913L.2**

PUBLIC NOTICE of NETWORK CHANGE UNDER RULE 51.329(a)

Network Disclosure Number: ATT20160913L.2

Issue Date: 09/16/2016  
 Modification Date: On or After 2<sup>nd</sup> Qtr 2017

Carrier's Name: AT&T Southwest

Carrier's Address: 2800 W 10<sup>th</sup> St. Sioux Falls, SD 57104

Contact: Your Account Manager or Service Representative  
**Technical Issues**  
 Terry McKenzie  
 2800 W 10<sup>th</sup> St.  
 Sioux Falls, SD 57014  
 605-530-9456  
[tm921b@att.com](mailto:tm921b@att.com)

Public Notice: **can be obtained on the Internet at:**  
<https://ebiznet.att.com/networkreg/>

**Network Change:**

This is a revision to the short term network change notice **ATT20150911S.1 rev2**. The reason for this revision is the due date is not obtainable due to network freezes and AT&T is extending the window of implementation to on or after 2<sup>nd</sup> quarter 2017 to meet these ASR/LSR obligations for carrier rehomng. **AT&T Southwest** has developed a project with the plan to eliminate the Nortel DMS STPs in Longview/Tyler, Texas. This will require re-homing all the SS7 linksets from the Longview/Tyler Nortel DMS STPs (**LGVWTXPL01W/TYLRTXLY03W**) into the Dallas/FortWorth, Texas (**DLLSTXTA38W/FTWOTXED36W**) Tekelec STPs. This change will consolidate STPs in LATA (554) to LATA (552).

**Description of Type of Changes Planned:**

AT&T Southwest will be decommissioning the STPs in the AT&T Longview/Tyler, TX area. Carriers who connect with AT&T in the Longview/Tyler LATA (554) need to migrate their SS7 linksets. The NEW FSPOI codes are (**LGVWTXPL0JW/TYLRTXLY0MW**). AT&T will transport the SS7 links from the FSPOI to the new STP location in LATA 552.

**Longview/Taylor- LATA-554**  
 LGVWTXPL01W / TYLRTXLY03W  
 Point Code - 249-039-000 / 249-038-000---Alias 249-087-000

**Dallas/Fort Worth-LATA-552**  
 DLLSTXTA38W / FTWOTXED36W  
 Point Code - 249-030-000 / 249-031-000--Alias 249-096-000

**Description of Reasonably Foreseeable Impact of the Planned Changes:**

Carriers will need to move their SS7 links and must coordinate the activity with AT&T. AT&T will communicate more details with affected Carriers in 2<sup>nd</sup> Quarter 2016. It is anticipated that Carriers will have to issue ASRs to connect to the FSPOI in the existing LATA (562) and that **Carriers will not have to transport their SS7 links any further than they presently do.** ASRs will need to be issued prior to the cutovers with the existing FSPOI, and the new Far End CLLI and Point Code. The Carriers will need a technician in their Central Office or STP during the maintenance window on the night of the cutover to make changes in the SS7 routing tables with the new set of point codes shown above. Acknowledgement of this disclosure (ASR/LSRs) and *intent* for traffic is requested by **12/1/16**.

**Location of Change:**

CLLI Code/Statewide	City	State	Implementation Date
LGVWTXPL01W / TYLRTXLY03W	Longview/Tyler	Texas	On or After 2 <sup>nd</sup> Qtr 2017
To	Dallas/Ft. Worth	Texas	On or After 2 <sup>nd</sup> Qtr 2017
DLLSTXTA38W / FTWOTXED36W			