

BELLSOUTH

BellSouth Corporation
Suite 900
1133-21st Street, N.W.
Washington, D.C. 20036-3351

mary.henze@bellsouth.com

February 11, 2002

Ms. Magalie R. Salas
Secretary
Federal Communications Commission
445 Twelfth Street, S.W., Room TW-A325
Washington, DC 20554

Re: BellSouth's Public Notice of Network Change
Under Rule 51.329(a) - CC Docket No. 96-98

Dear Ms. Salas:

BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Public Notice of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. Descriptions of the changes are provided below:

Number	Type of Change Planned	Location of Change
SN91082841	Cable Rearrangements to Upgrade ADSL Lines and Equipment	Starkville, Mississippi

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division. A copy of this notice is also available at:

<http://www.interconnection.bellsouth.com/notifications/network/index.html>

Should you have any questions regarding this submission, please contact me at (202) 463-4109.

Sincerely,



Mary L. Henze
Executive Director, Federal Regulatory

Attachment

cc: Diane Griffin Harmon (with diskette)
Carmell Weathers (with diskette)

Mary L. Henze
Executive Director
Federal Regulatory Affairs

DOCKET FILE COPY ORIGINAL 202 463-4109
202 463-4631 Fax

RECEIVED

FEB 11 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

No. of Copies rec'd 0+2
List A B C D E

**Notice of Network Change
Cable Rearrangements to Upgrade ADSL Lines and Equipment**

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: BellSouth rearrangements will need to be completed by August 8 2002

Location of Changes: Starkville, Mississippi – Connect points at 804 S Montgomery St. @ Academy Rd., P 1000 S Montgomery St. @ Sherwood Rd., and F 101 Brook Av. @ Greenbriar St. All terminals served by the above three connect points working along and east & west of S. Montgomery St. from 804 S. Montgomery St. south through Colonial Circle and Oakwood St.

Description of Change Planned: Add ADSL remote DSLAM @ 804 S. Montgomery St. and extend remote ADSL pairs to P 1000 S Montgomery St and F 101 Brook Avenue.

Description of Reasonably Foreseeable Impact of the Planned Change: There will be a significant difference in signal level, between those ADSL lines provided from the remote solution, and those ADSL lines provided via metallic cable from the Central Office (CO). There is a small chance that the service provided via the latter could be significantly impaired via crosstalk. In such an event, BellSouth will work with the affected service providers to remediate the problem.

Contact: Technical questions relating to this change should be directed to: Wayne C. Leach, Loop Capacity Manager
175 E Capitol St, Room 5040
Jackson, MS 39201
(601) 961-1301

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191