



Steven D. Long
Assistant Manager
Federal Regulatory

AT&T Services Inc.
1120 20th Street, NW
Suite 1000
Washington, DC 20036

T: 202.457.2047
F: 202.457.3072

March 22, 2007

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 Twelfth Street SW
Washington, DC 20554

Re: Notices of Network Change Under Rule 51.329(a)
CC Docket No. 96-98

Dear Ms. Dortch:

AT&T Southeast (formerly BellSouth Telecommunications, Inc.) hereby submits its Notice of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
20070031	Replace Copper with Fiber	Bentley, LA
20070032	Replace Copper with Fiber	Miami, FL

This notice is also available at:

http://www.interconnection.bellsouth.com/alerts_and_notifications

If you have any questions, please contact me at (202) 457-2047.

Sincerely,

/s/ Steven D. Long

Attachments

cc: Carmell Weathers

**Notice of Network Change – Hwy 167 North, Bentley, LA
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems**

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: Fourth Quarter 2007

Location of Changes: Areas in and around Bentley, LA in the Dry Prong "Main" wire center".

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact:	<u>Technical questions</u> relating to this change should be directed to:	Gary L. Fillette 825 Murray St. Alexandria, LA 71303 318-473-1746
-----------------	---	--

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 1-888-557-0667

Outside BellSouth region: 1-800-786-7619

Fax: 1-205-321-2191

Attachment

Notice of Network Change – Miami, FL
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: October 31, 2007, by the end of business day (5:00pm EDT).

Location of Changes: *The 4 Xboxes being treated cover the following area: NW 4th St on the North, NW S River Dr on the East, NW 1st St on the South, and NW 10th Av on the West side, in the Metro Wirecenter, in Miami, Florida.*

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: The work is necessary to replace existing copper feeder cables that are currently in conflict with the Army Corps of Engineers' Federal Dredging Project of the Miami River. After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact: <u>Technical questions</u> relating to this change should be directed to:	Miguel A. Gomez 9101 SW 24 th St Miami, Florida 33165 305-222-8748
---	--

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 1-888-557-0667

Outside BellSouth region: 1-800-786-7619

Fax: 1-205-321-2191

Attachment

Notice of Network Change Under Rule 51.329(a)
Notification No. ND20070032
Issue Date: March 21, 2007