

Changing my MMSI number on a Standard Horizon Spectrum VHF will have to be a return to factory job. This seems a petty solution to a database problem that originated with the system manager - the issuing agency! Why not get the Boat US issued MMSI numbers to record as valid international numbers: perhaps a more difficult solution - but one that should not be passed off to the users.