
TXU triplex
Top of conduit
3'-0"
2'-0"
4'-1"
Verizon Business
TWC
Ver Busi
AT&T
12

Top of Conduit
TWC
Ver Boss
AT&T


TXU Triplex
Top of Conduit
2'-3"
TWC


Bottom Transformer
TXU Triplex
TXU Triplex
Top of Conduit
3'-0"
2'-3"
1'-6"
(TWC)
2'-8"
3'-9"
(VB)
(AT&T)
TXU Triplex
TWC
Ver Busi
AT&T
15

TWC
Yes Busi
AT&T
Top of Conduit
Broken Arrester
Grounding Conductor

Bottom Transfmr
To TWC 1'-0"
To VB 2'-4"
Upper Conduit
4"
1'-8"
2'-9"
Lower Conduit
Top of lower Conduit below all communication
TWC
Ver Business
A TET
17


Broken Surge
Arrester
Grounding Conductor
18


Triplex to:
TWC - 2'-0"
VB - 3'-0"
U-Guard to:
TWC 1'-10"
VB 3'-10"
Drip loops
Drip loops
7"
1'-7"
3'-2"
TXU triplex
TWC
VB
AT&T

TXU triplex
TWC
Jer Business
AT&T
Drip loops to riser
U-guard
20

20'-6"
21


TXU Neutral
TXU St Lt Twin -
Below TWC
TWC
22

TXU Broken St Lt Twin
Dead-end clamp
TXU Neutral
TXU St Lt Twin –
Sagging below TWC
TWC
23

1'-11"
TXU St Lt Twin
TWC
24


TXU work in progress
(4/25/2008)
TXU Neutral
TCJC
TXU service drop/
transformer leads
droped across
TCJC
25


TXU Polework completed
TXU service drop Not connected
TXU Neutral
TWC

26


TXU Work in Progress
(4/25/2008)
TXU Neutral
TWC
TXU service drop/transformer leads coiled and tied to TWC
27


TXU Work Completed
TXU Service
TXU Neutral
TXU Transformer leads
37"
TWC
Kelsie

28


Conduit ends at City cable
City
TUC
AT&T (lower)
AT&T
New Service Conduit