



Victoria Carter-Hall
Manager - Federal Regulatory

AT&T Services, Inc.
1120 20th Street, NW
10th Floor
Washington, DC 20036
202.457.2164
Email: vc3624@att.com

July 13, 2016

Ms. Marlene H. Dortch, Secretary
Federal Communications Commission
445 12th Street, S.W.
Washington, DC 20554

**Re: Certification of Public Notice of Network Change under Rule 51.329(a)
CC Docket No. 96-98**

Dear Ms. Dortch:

Pursuant to the notification requirements in §51.325 -- §51.335 of the Commission's rules, AT&T hereby submits this certification of Public Notice of Network Change. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
ATT20160713L.1	<p>The purpose of this Network Disclosure is to provide information on the Odessa Lincoln Federal (ODSSTXLICG0) Transfer Project and Dial with Dial plans. AT&T Southwest is replacing the existing Alcatel Lucent 1AESS standalone end office switch with a new Genband switch utilizing the G6/G5 architecture. The GENBAND switch is configured to accept trunking in TDM format only. The existing switch, ODSSTXLICG0 will be Dial with Dialed to the new switch, ODSSTXLIPSA, during the 1st or 2nd Qtr 2017.</p> <p>Currently, ODSSTXLICG0, homes on MDLDTXMU15T (Midland - Mutual) for FG B, FG D and Intra Lata tandem functions. The <i>new</i>, ODSSTXLIPSA, switch will also home on the MDLDTXMU15T (Midland - Mutual) for FG B, FG D Intra Lata tandem functions.</p> <p>ODSSTXLICG0 currently homes on the MDLDTXMU15T (Midland - Mutual) for Operator Services. The new ODSSTXLIPSA switch will also home on the MDLDTXMU15T (Midland - Mutual) for Operator Services.</p>	Odessa, TX

Ms. Marlene H. Dortch, Secretary

Page 2

July 13, 2016

	<p>Existing CLLI code: ODSSTXLICG0 Existing Point Code: 249 135 002 New CLLI code: ODSSTXLIPSA New Point Code: 249 138 136 (same as Call Agent FTWOTXEDDC9) LATA: 542 NPA: 432 NXXs*: 331 through 335; 337, 580, 582.</p> <p>*NXXs valid as of 11/2/2015.</p>	
--	---	--

This notice is also available at: <https://ebiznet.att.com/networkreg/>

If you have any questions, please do not hesitate to contact me at (202) 457-2164.

Sincerely,



Victoria Carter-Hall

Attachments

cc: Carmell Weathers

**CERTIFICATION OF PUBLIC NOTICE(S) OF NETWORK
CHANGE(S) UNDER RULE 51.329(a)**

On **July 13, 2016** the following Public Notice(s) of Network Change(s) have been made by
AT&T Southwest Pursuant to Code of Federal Regulations 47, Subsections 51.325 – 51.335.



Terry L McKenzie
Manager - Regulatory Relations
Telephone: (605) 530-9456 Date: 07/13/2016

The Public Notice(s) can also be obtained on the Internet at:

<https://ebiznet.att.com/networkreg/>

Title(s) of Network Notification(s):

ATT20160713L.1

PUBLIC NOTICE of NETWORK CHANGE UNDER RULE 51.329(a)

Network Disclosure Number: ATT20160713L.1 Issue Date: 07/13/2016
Modification Date: 1st or 2nd Qtr 2017

Carrier's Name: AT&T Southwest

Carrier's Address: 2800 W 10th St. Sioux Falls, SD 57104

Contact: Your Account Manager or Service Representative

Technical Issues

Terry McKenzie
2800 W 10th St.
Sioux Falls, SD 57014
605-530-9456
tm921b@att.com

Public Notice: **can be obtained on the Internet at:**

<https://ebiznet.att.com/networkreg/>

Network Change:

AT&T Southwest is announcing that the Alcatel-Lucent 1AESS switch at Odessa Lincoln Federal (ODSSTXLICG0) is being replaced with a GENBAND switch utilizing G6/G5 architecture. The cutover is scheduled for the 1st or 2nd Qtr 2017 and will not happen before February 10, 2017.

Description of Type of Changes Planned:

The purpose of this Network Disclosure is to provide information on the Odessa Lincoln Federal (ODSSTXLICG0) Transfer Project and Dial with Dial plans. AT&T Southwest is replacing the existing Alcatel Lucent 1AESS standalone end office switch with a new Genband switch utilizing the G6/G5 architecture. The GENBAND switch is configured to accept trunking in TDM format only. The existing switch, ODSSTXLICG0 will be Dial with Dialed to the new switch, ODSSTXLIPSA, during the 1st or 2nd Qtr 2017.

Currently, ODSSTXLICG0, homes on MDLDTXMU15T (Midland - Mutual) for FG **B**, FG **D** and Intra Lata tandem functions.

The *new*, ODSSTXLIPSA, switch will also home on the MDLDTXMU15T (Midland - Mutual) for FG **B**, FG **D** Intra Lata tandem functions.

ODSSTXLICG0 currently homes on the MDLDTXMU15T (Midland - Mutual) for Operator Services.

The new ODSSTXLIPSA switch will also home on the MDLDTXMU15T (Midland - Mutual) for Operator Services.

Existing CLI code: ODSSTXLICG0

Existing Point Code: 249 135 002

New CLI code: ODSSTXLIPSA

New Point Code: 249 138 136 (same as Call Agent FTWOTXEDDC9)

LATA: 542 NPA: 432 NXXs*: 331 through 335; 337, 580, 582.

*NXXs valid as of 11/2/2015.

Description of Reasonably Foreseeable Impact of the Planned Changes:

AT&T Southwest, Independent LECs, Wireless Service Providers, IXC and CLECs will be affected for traffic originating and Terminating to and from end office (ODSSTXLICG0). All existing trunking to ODSSTXLICG0 can be **migrated** to the ODSSTXLIPSA switch.

Independent LECs, Wireless Service Providers, IXC and CLECs must **(a)** determine whether to establish new trunk groups to ODSSTXLIPSA, if appropriate, and **(b)** evaluate whether their existing trunk groups to MDLDTXMU15T (Midland - Mutual) are adequate to handle the ODSSTXLIPSA traffic.

Acknowledgement of this disclosure (ASR/LSRs) and *intent* for traffic is requested by **12/1/16**.

Location of Change:

CLLI Code/Statewide	City	State	Implementation Date
(ODSSTXLICG0)	Odessa	Texas	1st or 2nd Qtr 2017
To			
(ODSSTXLIPSA)	Odessa	Texas	1st or 2nd Qtr 2017