



Victoria Carter-Hall  
Manager - Federal Regulatory

AT&T Services, Inc.  
1120 20<sup>th</sup> St., NW, Suite 1000  
Washington, DC 20036  
T: 202.457.2164

November 7, 2018

Ms. Marlene H. Dortch, Secretary  
Federal Communications Commission  
445 12<sup>th</sup> Street, S.W.  
Washington, DC 20554

**Re: Certification of Public Notice of Network Change under Rule 51.329(a)**  
**CC Docket No. 96-98**

Dear Ms. Dortch:

Pursuant to the notification requirements in §51.325 -- §51.335 of the Commission's rules, Southwestern Bell Telephone Company d/b/a AT&T Texas (AT&T) hereby submits this certification of Public Notice of Network Change (ATT20181107L.1). A description of the network change is provided below:

<u>Number</u>	<u>Type of Change Planned</u>	<u>Location of Change</u>
<b>ATT20181107L.1</b>	<b>AT&amp;T Texas</b> , is announcing that the HSTNTX0801T ( <b>3303 Wesleyan St, Houston, TX 77027</b> ), DMS200 Local Tandem switch will be decommissioned from the network in 1 <sup>st</sup> Qtr 2020. All traffic and trunks currently transiting the 01T switch should be migrated to HSTNTX0806T ( <b>Same Building</b> ). (The HSTNTX0806T switch is also known as HSTNTX08DS2 in some databases). All traffic on the Houston, TX, Wesleyan, 01T (HSTNTX0801T) Access tandem switch will be migrated to the Houston, TX, Wesleyan, 06T (HSTNTX0806T) Access tandem. The 01T switch will be powered down and removed from service. Existing CLLI code: HSTNTX0801T (DMS100) Existing Point Code: 249.147.100 New CLLI code: HSTNTX0806T New Point Code: 249.147.124 LATA: 560	<b>Houston, TX</b>

This notice is also available at: <https://ebiznet.att.com/networkreg/>. If you have any questions, please do not hesitate to contact me at (202) 457-2164.

Sincerely,

Victoria Carter-Hall

Attachments

cc: Carmell Weathers

## **CERTIFICATION OF PUBLIC NOTICE(s) OF NETWORK CHANGE(s) UNDER RULE 51.329(a)**

On **November 7, 2018** the following Public Notice(s) of Network Change(s) have been made by **Southwestern Bell Telephone Company d/b/a AT&T Texas** Pursuant to Code of Federal Regulations 47, Subsections 51.325 – 51.335.



Richard Hatch  
Area Manager - Regulatory Relations  
Telephone: 479-253-7675                      Date: 11/07/2018

The Public Notice(s) can also be obtained on the Internet at:

<https://ebiznet.att.com/networkreg/>

### **Title(s) of Network Notification(s):**

**ATT20181107L.1**

# PUBLIC NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

**Network Disclosure  
Number:**

**ATT20181107L.1**

**Issue Date: 11/07/2018**

**Carrier's Name:**

Southwestern Bell Telephone Company d/b/a AT&T  
Texas

**Carrier's Address:**

1120 20<sup>th</sup> Street NW, Suite 1000, Washington, DC 20036

**Contact:**

Your Account Manager or Service Representative

**Technical Issues**

Richard Hatch  
135 Huntsville Rd  
Eureka Springs, AR 72632  
479-253-7675  
[rh4979@att.com](mailto:rh4979@att.com)

**Public Notice:** can be obtained on the Internet at:  
<https://ebiznet.att.com/networkreg/>

**Implementation Date:** On or after March 31, 2020

**Description of Network Changes Planned:**

**AT&T Texas**, is announcing that the **HSTNTX0801T (3303 Wesleyan St, Houston, TX 77027)**, DMS200 Local Tandem switch will be decommissioned from the network in 1<sup>st</sup> Qtr 2020. All traffic and trunks currently transiting the 01T switch should be migrated to **HSTNTX0806T (Same Building)**. (The HSTNTX0806T switch is also known as HSTNTX08DS2 in some databases). All traffic on the Houston, TX, Wesleyan, 01T (HSTNTX0801T) Access tandem switch will be migrated to the Houston, TX, Wesleyan, 06T (HSTNTX0806T) Access tandem. The 01T switch will be powered down and removed from service.

Existing CLLI code: HSTNTX0801T (DMS100)

Existing Point Code: 249.147.100

New CLLI code: HSTNTX0806T

New Point Code: 249.147.124

LATA: 560

**Description of Reasonably Foreseeable Impact of the Planned Changes:**

AT&T Texas, Independent LECs, Wireless Service Providers, and CLECs will be affected for current traffic routing through the **HSTNTX0801T** Local tandem.

- All existing trunking to **HSTNTX0801T** will need to be **disconnected**.
- An existing trunk group to the **HSTNTX0806T** Access Tandem, should be utilized, and if necessary augmented.
- If an existing trunk group does not exist to 06T, then an appropriate trunk group should be established to the **HSTNTX0806T** Access Tandem.
- Interexchange Carriers, Independent LECs, Wireless Service Providers, and CLECs must:
  - (a) determine if existing trunk groups to **HSTNTX0806T** are adequate to handle the traffic; and
  - (b) take appropriate action by August 31, 2019, to begin the transfer of the traffic to **HSTNTX0806T**.

Access Service Requests (ASR) or Local Service Requests (LSR) are due to be submitted on or prior to September 1, 2019, and traffic migration complete by January 1, 2020.