



**Victoria Carter-Hall**  
Manager - Federal Regulatory

AT&T Services, Inc.  
1120 20<sup>th</sup> St., NW, Suite 1000  
Washington, DC 20036  
T: 202.457.2164  
F: 202.457.3072

November 9, 2017

Ms. Marlene H. Dortch, Secretary  
Federal Communications Commission  
445 12<sup>th</sup> Street, S.W.  
Washington, DC 20554

**Re: Certification of Public Notice of Network Change under Rule 51.329(a)**  
**CC Docket No. 96-98**

Dear Ms. Dortch:

Pursuant to the notification requirements in §51.325 -- §51.335 of the Commission's rules, AT&T hereby submits this certification of Public Notice of Network Change. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
<b>ATT20171107L.1</b>	<p>AT&amp;T Texas is replacing the existing Ericsson Remote switch at the Dayton, TX office with a new Genband switch utilizing the GENBAND G6/G5 architecture.</p> <p>The existing switch, DAYTON, TX (DYTN TXDYRS0), will be Dial with Dialed to (DYTN TXDYPSA), on or after June, 2018.</p> <p>Currently DYTN TXDYRS0 homes on the HSTN TXJA05T (Houston Jackson) for FG B and FG D tandem functions. The new DYTN TXDYPSA will keep the same FG homing arrangements.</p> <p>Currently DYTN TXDYRS0 homes on the HSTN TXJA07T (Houston Jackson) for Local (LATA) tandem functions. The new DYTN TXDYPSA will keep the same Local LATA homing arrangements.</p> <p>Currently DYTN TXDYRS0 homes on the HSTN TX0802T (Houston National) Operator Services Tandem.</p> <p>The new (DYTN TXDYPSA) location will keep the same arrangement</p> <p>Existing CLLI code: DAYTON, TX (DYTN TXDYRS0)</p> <p>Existing Point Code: 249 147 096 (Current Host – Liberty, TX (LBRT TXLBDS0)</p> <p>New CLLI code: (DYTN TXDYPSA)</p> <p>New Point Code: 249 138 136 (same as FTWOTXEDPSA)</p> <p>LATA: 560      NPA: 936      NXXs*: 257; 258.</p> <p>*NXXs valid as of 9/20/2017.</p>	<b>Dayton, TX</b>

This notice is also available at: <https://ebiznet.att.com/networkreg/>

If you have any questions, please do not hesitate to contact me at (202) 457-2164.

Sincerely,

Victoria Carter-Hall

Attachments

cc: Carmell Weathers

## **CERTIFICATION OF PUBLIC NOTICE(s) OF NETWORK CHANGE(s) UNDER RULE 51.329(a)**

On 11/9/2017 the following Public Notice(s) of Network Change(s) have been made by Southwestern Bell Telephone Company d/b/a AT&T Texas pursuant to Code of Federal Regulations 47, Subsections 51.325 – 51.335.



Terry L. McKenzie  
Manager - Regulatory Relations  
Telephone: (605) 530-9456      Date: 11/9/2017

The Public Notice(s) can also be obtained on the Internet at:

<https://ebiznet.att.com/networkreg/>

### **Title(s) of Network Notification(s):**

ATT20171107L.1

## PUBLIC NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

**Network Disclosure  
Number:**

**ATT20171107L.1**

---

**Issue Date: 11/9/2017**

**Carrier's Name:**

Southwestern Bell Telephone Company d/b/a AT&T  
Texas

---

**Carrier's Address:**

1120 20<sup>th</sup> Street NW, Suite 1000, Washington, DC 20036

---

**Contact:**

Your Account Manager or Service Representative

**Technical Issues**

Terry McKenzie  
2800 W 10Th St  
Sioux Falls, SD 57104  
(605) 530-9456  
[tm921b@att.com](mailto:tm921b@att.com)

---

**Public Notice:** **can be obtained on the Internet at:**  
<https://ebiznet.att.com/networkreg/>

---

**Implementation Date: On or after June 2018**

**Description of Network Changes Planned:**

AT&T Texas is replacing the existing Ericsson Remote switch at the Dayton, TX office with a new Genband switch utilizing the GENBAND G6/G5 architecture.

The existing switch, DAYTON, TX (DYTNXXDYRS0), will be Dial with Dialed to (DYTNXXDYPSA), on or after June, 2018.

Currently DYTNXXDYRS0 homes on the HSTNXXJA05T (Houston Jackson) for FG B and FG D tandem functions. The new DYTNXXDYPSA will keep the same FG homing arrangements.

Currently DYTNXXDYRS0 homes on the HSTNXXJA07T (Houston Jackson) for Local (LATA) tandem functions.

The new DYTNXXDYPSA will keep the same Local LATA homing arrangements.

Currently DYTNXXDYRS0 homes on the HSTNXX0802T (Houston National) Operator Services Tandem.

The new (DYTNXXDYPSA) location will keep the same arrangement

Existing CLLI code: DAYTON, TX (DYTNXXDYRS0)

Existing Point Code: 249 147 096 (Current Host – Liberty, TX (LBRTXXLBDS0)

New CLLI code: (DYTNXXDYPSA)

New Point Code: 249 138 136 (same as FTWOTXEDPSA)

LATA: 560 NPA: 936 NXXs\*: 257; 258.

\*NXXs valid as of 9/20/2017.

**Description of Reasonably Foreseeable Impact of the Planned Changes:**

AT&T Texas, Independent LECs, Wireless Service Providers, CLECs and Interexchange Carriers will now have the opportunity to trunk to Dayton (DYTNXXDYPSA).

Direct Inward Dialing (DID) or Outward Dialing (DOD) Trunking will need to be migrated to Dayton (DYTNXXDYPSA). Independent LECs, Wireless Service Providers, CLECs

and Interexchange Carriers must (a) determine whether to establish new trunk groups to Houston Jackson (HSTNTXJA05T), Access Tandem, or Houston Jackson (HSTNTXJA07T, local tandem, if appropriate, and (b) evaluate whether their existing trunk groups to the appropriate tandem are adequate to handle Dayton traffic. Access Service Requests (ASR) or Local Service Requests (LSR) will be due by 3/09/18.

Project will not be completed prior to June 9, 2018.