



Victoria Carter-Hall  
Manager - Federal Regulatory

AT&T Services, Inc.  
1120 20<sup>th</sup> Street, NW  
10<sup>th</sup> Floor  
Washington, DC 20036  
202.457.2164  
Email: [vc3624@att.com](mailto:vc3624@att.com)

April 6, 2016

Ms. Marlene H. Dortch, Secretary  
Federal Communications Commission  
445 12<sup>th</sup> Street, S.W.  
Washington, DC 20554

**Re: Certification of Public Notice of Network Change under Rule 51.329(a)  
CC Docket No. 96-98**

Dear Ms. Dortch:

Pursuant to the notification requirements in §51.325 -- §51.335 of the Commission's rules, AT&T hereby submits this certification of Public Notice of Network Change. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
ATT20160201L.1 Rev1	<p>AT&amp;T Southwest will be decommissioning the STPs in the AT&amp;T El Paso, TX area. Carriers who connect with AT&amp;T Southwest in the El Paso LATA (540) need to migrate their SS7 linksets.</p> <p>The NEW FSPOI codes are <b>ELPSTXEA0AW/ELPSTXMA1QW</b>. AT&amp;T will transport the SS7 links from the FSPOI to the new STP location in LATA 558.</p> <p><b>El Paso - LATA-540</b> ELPSTXEA04W/ELPSTXMA05W Point Code - 249-048-000/249-049-000 - Alias 249-082-000</p> <p><b>Austin-LATA-558</b> AUSTTXGR57W/AUSTTXTE13W Point Code - 249-012-000/249-013-000 - Alias 249-151-251</p>	<p>El Paso, TX</p> <p>Austin, TX</p>

This notice is also available at: <https://ebiznet.att.com/networkreg/>

If you have any questions, please do not hesitate to contact me at (202) 457-2164.

Sincerely,

Victoria Carter-Hall

Attachments

cc: Carmell Weathers

**CERTIFICATION OF PUBLIC NOTICE(s) OF NETWORK  
CHANGE(s) UNDER RULE 51.329(a)**

On **April 5, 2016** the following Public Notice(s) of Network Change(s) have been made by **AT&T Southwest** Pursuant to Code of Federal Regulations 47, Subsections 51.325 – 51.335.



Terry L McKenzie  
Manager - Regulatory Relations  
Telephone: (605) 530-9456

Date: 04/05/2016

The Public Notice(s) can also be obtained on the Internet at:

<https://ebiznet.att.com/networkreg/>

**Title(s) of Network Notification(s):**

**ATT20160201L.1 rev1**

PUBLIC NOTICE of NETWORK CHANGE UNDER RULE 51.329(a)

Network Disclosure Number: ATT20160201L.1 rev1

Issue Date: 04/05/2016

Modification Date: 1st Qtr 2017

Carrier's Name: AT&T Southwest

Carrier's Address: 3220 W. 57<sup>th</sup> St. Sioux Falls, SD 57108

Contact: Your Account Manager or Service Representative

**Technical Issues**

Terry McKenzie  
3220 W 57<sup>th</sup> St.  
Sioux Falls, SD 57108  
605 530-9456  
[tm921b@att.com](mailto:tm921b@att.com)

Public Notice: **can be obtained on the Internet at:**

<https://ebiznet.att.com/networkreg/>

**Network Change:**

This is the first revision to the Network Change Disclosure **ATT20160201L.1**. The revision extends the rehome into the 1<sup>st</sup> Quarter of 2017 due to Network Freezes in the 4<sup>th</sup> quarter. The original 4<sup>th</sup> Qtr date could not be met. **AT&T Southwest** has developed a project with the plan to eliminate the Nortel DMS STPs in El Paso, Texas. This will require re-homing all the SS7 linksets from the El Paso Nortel DMS STPs (**ELPSTXEA04W/ELPSTXMA05W**) into the Austin, Texas (**AUSTTXGR57W/AUSTTXTE13W**) Tekelec STPs. This change will consolidate STPs in LATA (540) to LATA (558).

**Description of Type of Changes Planned:**

AT&T Southwest will be decommissioning the STPs in the AT&T El Paso, TX area. Carriers who connect with AT&T Southwest in the El Paso LATA (540) need to migrate their SS7 linksets. The NEW FSPOI codes are **ELPSTXEA04W/ELPSTXMA1QW**. AT&T will transport the SS7 links from the FSPOI to the new STP location in LATA 558.

**El Paso - LATA-540**

ELPSTXEA04W/ELPSTXMA05W

Point Code - 249-048-000/249-049-000 - Alias 249-082-000

**Austin-LATA-558**

AUSTTXGR57W/AUSTTXTE13W

Point Code - 249-012-000/249-013-000 - Alias 249-151-251

**Description of Reasonably Foreseeable Impact of the Planned Changes:**

Carriers will need to move their SS7 links and must coordinate the activity with AT&T. AT&T will communicate more details with affected Carriers in 4th Quarter 2016. It is anticipated that Carriers will have to issue ASRs to connect to the FSPOI in the existing LATA (540) and that **Carriers will not have to transport their SS7 links any further than they presently do**. ASRs will need to be issued prior to the cutovers with the existing FSPOI, and the new Far End CLLI and Point Code. The Carriers will need a technician in their Central Office or STP during the maintenance window on the night of the cutover to make changes in the SS7 routing tables with the new set of point codes shown below.

**Location of Change:**

CLLI Code/Statewide	City	State	Implementation Date
From ELPSTXEA04W / ELPSTXMA05W	El Paso	TX	1st Qtr. 2017
To AUSTTXGR57W / AUSTTXTE13W	Austin	TX	1st Qtr. 2017