

BELLSOUTH

BellSouth Corporation
Suite 900
1133-21st Street, N W
Washington, D C. 20036-3351

maryhenze@bellsouth.com

Mary L. Henze
Executive Director
Federal Regulatory Affairs

202463 4109
Fax 202 463 4631

DOCKET FILE COPY ORIGINAL

December 16, 2002

RECEIVED

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 Twelfth Street, S.W.
Washington, DC 20554

Re: Notices of Network Change Under Rule 51.329(a) CC Docket No. 96-98

Dear Ms. Dortch:

BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Notices of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
91083442	Central Office Conversion	Leland, Mississippi
91083453	Central Office Conversion	Scooba, Mississippi
91083455	Central Office Conversion	Shuqualak, Mississippi
91083459	Central Office Conversion	Ethel, Mississippi
91083460	Central Office Conversion	McCool, Mississippi
91083461	Central Office Conversion	Goodman, Mississippi
91083462	Central Office Conversion	Seminary, Mississippi
91083463	Central Office Conversion	Tchula, Mississippi
91083464	Central Office Conversion	Kosciusko, Mississippi
91083465	Central Office Conversion	Macon, Mississippi
91083466	Central Office Conversion	West, Mississippi
91083467	Central Office Conversion	Magee, Mississippi
91083468	Central Office Conversion	Durant, Mississippi

No. of Copies rec'd

ABCDE

9/12


Number	Type of Change Planned	Location of Change
91083469	Central Office Conversion	Rolling Fork, Mississippi
91083470	Central Office Conversion	Hollandale, Mississippi
91083471	Central Office Conversion	Brooksville, Mississippi
91083501	Central Office Conversion	Macon, Georgia
91083494	Replace Copper to Fiber	Houma, Louisiana
91083508	Replace Copper to Fiber	Shelby, North Carolina
91083513	Replace Copper to Fiber	W. Palm Beach, Florida
91083514	Replace Copper to Fiber	Huntsville, Alabama

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division. A copy of the notice is also available at:

<http://www.interconnection.bellsouth.com/notifications/network/index.html>

Should you have any questions regarding this submission, please contact me at (202) 463-4109.

Sincerely,



Mary L. Henze
Executive Director - Federal Regulatory

Attachments

cc: Michelle Carey (with diskette)
Carmell Weathers (with diskette)

RECEIVED

Notice of Network Change - Leland, Mississippi Central Office Conversion

DEC 16 2002

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, December 13, 2003, 12:01 AM Central Standard Time

Location of Changes: Leland, Mississippi

Description of Change Planned: Leland, Mississippi Central Office Conversion: The Siemens Stornberg-Carlson DCO remote switch (LEDLMSMADSO) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be LEDLMSMARS9 and the new point code will be 252-146-037. The new switch will be a remote working from the Indianola Host (INDNMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: 662 NXX: 686

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, December 5, 2003 through Sunday, December 14, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions relating to this change should be directed to: Karl Donnelly or Robert Cheadle, Managers - Network
6767 Bundy Road, First Floor North
New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region! 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083442
Issue Date: December 12, 2002

RECEIVED

Notice of Network Change - Scooba, Mississippi Central Office Conversion DEC 16 2002

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, September 20, 2003, 12:01 AM Central Daylight Time

Location of Changes: Scooba, Mississippi

Description of Change Planned: Scooba, Mississippi Central office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (SCOBMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be SCOBMSMARS9 and the new point code will be 252-146-081. The new switch will be a remote working from the Philadelphia Host (PHLAMSMADSZ). The following NXX code(s) will be affected with this conversion:

Areacode: 662 NXX: 476

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, September 12, 2003 through Sunday, September 21, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical Questions relating to this change should be directed to: Karl Donnelly or Robert Cheadle, Managers - Network
6767 Bundy Road, First Floor North
New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10 digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083453
Issue Date: December 12, 2002

RECEIVED

Notice of Network Change - Shuqualak, Mississippi Central Office Conversion **DEC 16 2002**

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, September 20, 2003, 12:01 AM Central Daylight Time

Location of Changes: Shuqualak, Mississippi

Description of Change Planned: Shuqualak, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (SHQLMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be SHQLMSMARS9 and the new point code will be 252-146-081. The new switch will be a remote working from the Philadelphia Host (PHLAMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: 662 **NXX: 793**

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, September 12, 2003 through Sunday, September 21, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-240-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

RECEIVED

Notice of Network Change - Ethel, Mississippi Central Office Conversion

DEC 16 2002

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, October 4, 2003, 12:01 AM Central Daylight Time

Location of Changes: Ethel, Mississippi

Description of Change Planned: Ethel, Mississippi Central **Office** Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (ETHLMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be ETHLMSMARS9 and the new point code will be 252-146-049. The new switch will be a remote working from the Grenada Host (GRNDMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: 662 **NXX:** 674

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A-service order freeze will be in effect from Friday, September 26, 2003 through Sunday, October 5, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your **local** area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083459
Issue Date: December 12, 2002

Notice of Network Change – McCool, Mississippi Central Office Conversion **DEC 16 2002**

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, October 4, 2003, 12:01 AM Central Daylight Time

Location of Changes: McCool, Mississippi

Description of Change Planned: McCool, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (MCCLMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be MCCLMSMARSQ and the new point code will be 252-146-049. The new switch will be a remote working from the Grenada Host (GRNDMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: 662 **NXX: 547**

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, September 26, 2003 through Sunday, October 5, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are **calling** from a mandatory lodigit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

RECEIVED

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Notice of Network Change - Goodman, Mississippi Central Office Conversion

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, October 11, 2003, 12:01 AM Central Daylight Time

Location of Changes: Goodman, Mississippi

Description of Change Planned: Goodman, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (GDMNMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be GDMNMSMARS9 and the new point code will be 252-146-037. The new switch will be a remote working from the Indianola Host (INDNMSMADS2). The following NXX code(s) will be affected with this conversion:

Area Code: 662 **NXX:** 472

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October 3, 2003 through Sunday, October 12, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(if you are calling from a mandatory 10-digit calling area,
include **your local area code.**)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change - Seminary, Mississippi Central Office Conversion

RECEIVED

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, October 11, 2003, 12:01 AM Central Daylight Time

Location of Changes: Seminary, Mississippi

Description of Change Planned: Seminary, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (SNRYMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be SNRYMSMARS9 and the new point code will be 252-146-021. The new switch will be a remote working from the Laurel Host (LARLMSMADSO). The following NXX code(s) will be affected with this conversion:

Area Code: 601 NXX: 722

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) **forms** that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October 3, 2003 through Sunday, October 12, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions relating to this change should be directed to: Karl Donnelly or Robert Cheadle, Managers - Network
6767 Bundy Road, First Floor North
New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local **area code**.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change – **Tchula**, Mississippi Central Office Conversion

RECEIVED

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, October 11, 2003, 12:01 AM Central Daylight Time

Location of Changes: Tchula. Mississippi

Description of Change Planned: Tchula. Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (TCHLMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be TCHLMSMARS9 and the new point code will be 252-146-037. The new switch will be a remote working from the Indianola Host (INDNMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: 662 **NXX: 235**

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October 3, 2003 through Sunday, October 12, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical Questions Karl Donnelly or Robert Cheadle. Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans. Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10 digit calling area,
include **your local area code.**)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083463
Issue Date: December 12, 2002

RECEIVED

Notice of Network Change - Kosciusko, Mississippi Central Office Conversion

DEC 16 2002

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, October 18, 2003, 12:01 AM Central Daylight Time

Location of Changes: Kosciusko, Mississippi

Description of Change Planned: Kosciusko, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RNS remote switch (KSCSMSMADSO) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be KSCSMSMARS9 and the new point code will be 252-146-049. The new switch will be a remote working from the Grenada Host (GRNDMSMADS2). The following NXX code(s) will be affected with this conversion:

Area Code: 662 NXX: 289,290

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A-service order freeze will be in effect from Friday, October 10, 2003 through Sunday, October 19, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN01083464
Issue Date: December 12, 2002

RECEIVED

Notice of Network Change - Macon, Mississippi Central Office Conversion

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, October **25, 2003, 12:01 AM** Central Daylight Time

Location of Changes: Macon, Mississippi

Description of Change Planned: Macon, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson DCO remote switch (MACNMSMADSO) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be MACNMSMARS9 and the new point code will be **252-146-081**. The new switch will be a remote working from the Philadelphia Host (PHLAMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: **662** **NXX: 726**

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October **17, 2003** through Sunday, October **26, 2003**. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or ~~critical~~ dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions relating to this change should be directed to: Karl Donnelly or Robert Cheadle, Managers - Network **6767** Bundy Road, First Floor North New Orleans, Louisiana **70127** **504-248-7727** or **504-248-7724**

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: **557-2647** (AL, KY, LA, MS, TN) or **780-2171** (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include your local area **code**.)

Outside BellSouth region: **1-800-786-7619**
Fax: **1-205-321-2191**

Notice of Network Change – West, Mississippi Central Office Conversion

RECEIVED

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

DEC 16 2002
FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, October 25, 2003, 12:01 AM Central Daylight Time

Location of Changes: West, Mississippi

Description of Change Planned: West, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (WESTMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be WESTMSMARS9 and the new point code will be 252-146-049. The new switch will be a remote working from the Grenada Host (GRNDMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: 662 **NXX:** 967

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October 17, 2003 through Sunday, October 26, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features

Contact: Technical Questions relating to this change should be directed to: Karl Donnelly or Robert Cheadle, Managers • Network
6767 Bundy Road, First Floor North
New Orleans, Louisiana 70127
504-248-7727 or ~~504-248-7724~~

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083466
Issue Date: December 12, 2002

Notice of Network Change - Magee, Mississippi Central Office Conversion

RECEIVED

DEC 16 2002

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, November 1, 2003, 12:01 AM Central Standard Time

Location of Changes: Magee, Mississippi

Description of Change Planned: Magee, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson DCO remote switch (MAGEMSMADSO) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be MAGEMSMARS9 and the new point code will be 252-146-021. The new switch will be a remote working from the Laurel Host (LARLMSMADSO). The following NXX code(s) will be affected with this conversion:

Areacode: 601 NXX: 849.867

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October 24, 2003 through Sunday, November 2, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local **area code**.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083467
Issue Date: December 12, 2002

RECEIVED

Notice of Network Change - Durant, Mississippi Central Office Conversion

DEC 16 2002

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, November 8, 2003, 12:01 AM Central Standard Time

Location of Changes: Durant, Mississippi

Description of Change Planned: Durant, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson DCO remote switch (DRNTMSMADSO) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be DRNTMSMARS9 and the new point code will be 252-146-037. The new switch will be a remote working from the Indianola Host (INDNMSMADSP). The following NXX code(s) will be affected with this conversion:

Areacode: 662 NXX: 653

Description of Reasonably Foreseeable **Impact** of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October 31, 2003 through Sunday, November 9, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Provider should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083468
Issue Date: December 12, 2002

RECEIVED

Notice of Network Change - Rolling Fork, Mississippi Central Office Conversion

DEC 16 2002

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, November 22, 2003, 12:01 AM Central Standard Time

Location of Changes: Rolling Fork, Mississippi

Description of Change Planned: Rolling Fork, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RNS remote switch (RLFKMSMADSO) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be RLFKMSMARS9 and the new point code will be 252-146-037. The new switch will be a remote working from the Indianola Host (INDNMSMADSP). The following NXX code(s) will be affected with this conversion:

Area Code: 662 **NXX:** 873

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, November 14, 2003 through Sunday, November 23, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions relating to this change should be directed to: Karl Donnelly or Robert Cheadle, Managers - Network
6767 Bundy Road, First Floor North
New Orleans, Louisiana 70127
504-248-7727 or ~~504-248-7724~~

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area **code**.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083469
Issue Date: December 12, 2002

RECEIVED

Notice of Network Change – Hollandale, Mississippi Central Office Conversion

DEC 16 2002

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, December 6, 2003, 12:01 AM Central Standard Time

Location of Changes: Hollandale, Mississippi

Description of Change Planned: Hollandale, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RNS remote switch (HODLMSMADSO) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be HODLMSMARS9 and the new point code will be 252-146-037. The new switch will be a remote working from the Indianola Host (INDNMSMADSP). The following NXX code(s) will be affected with this conversion:

Areacode: 662 **NXX:** 827

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, November 28, 2003 through Sunday, December 7, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or ~~504-248-7724~~

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory lodigit calling area,
include your local **area code**.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change – Brooksville, Mississippi Central Office Conversion

RECEIVED
version

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Saturday, September 20, 2003, 12:01 AM Central Daylight Time

Location of Changes: Brooksville, Mississippi

Description of Change Planned: Brooksville, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (BKVLMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be BKVLMSMARS9 and the new point code will be 252-146-081. The new switch will be a remote working from the Philadelphia Host (PHLAMSMADS2). The following NXX code(s) will be affected with this conversion:

Areacode: 662 NXX: 738

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSR) forms that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, September 12, 2003 through Sunday, September 21, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions relating to this change should be directed to: Karl Donnelly or Robert Cheadle, Managers - Network
6767 Bundy Road, First Floor North
New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change - Houma, Louisiana
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

RECEIVED

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Third Quarter 2003

Location of Changes: Montegut, Louisiana - All lines working south of 6603 Highway 56

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTSgrade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTSgrade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions relating to this change should be directed to: Pamela W. Keller - Specialist
1010 Hancock St.
Gretna, Louisiana 70053
504-363-3284

All other questions or **concerns** regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change - Shelby, NC
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

RECEIVED
DEC 16 2002
FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: July 15, 2003

Location of Changes: Shelby, NC: Old Boiling Springs Rd (SR 1123) from Hwy 150 north to intersection of SR 1123 and SR 1151. Eastern boundary is east fork of Beaverdam Creek. Western boundary is west fork of Beaverdam Creek.

Description of Change Planned: Copper facilities will be replaced with DLC

Description of Reasonably Foreseeable Impact of the Planned Change: Circuits will be transferred off copper cables by July 15, 2003. Circuits working on unbundled copper loops in this area will need to be moved off of the copper cables. After this work is completed metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g. Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier is providing DSL via a POTS-grade unbundled loop, BellSouth has no knowledge of the presence of DSL. The POTS-grade loop is considered to be compatible with DLC. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions Mark Burns
relating to this change 1520 Shannon Bradley Road
should be directed to: Gastonia, NC 28092
704861-6030

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083508
Issue Date: December 12, 2002

Notice of Network Change - West Palm Beach, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier **System**

Carrier

BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

RECEIVED
DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Ending 2nd Quarter 2003

Location of Changes: The Palm Club subdivision, Normandy Village and Villages of Palm Beach Lakes.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems due to DOT road improvements.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central **Office** to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTSgrade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled **loop** that has been defined to transport POTSgrade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions M L Johns
relating to this change 2021 S Military Tr.
should be directed to: West Palm Beach, FL 33415
561 439-9186

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10 digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change - Huntsville, Alabama
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

RECEIVED

DEC 16 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Date Changes are to Occur: Ending 2nd Quarter 2003

Location of Changes: Huntsville, AL - South Memorial Parkway all areas south of 8600 served from Huntsville-Parkway office.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service. BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions Michael C. Tolliver
relating to this change 308 Clinton Ave
should be directed to: Huntsville, AL 35801
256-532-8098

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notif of Network Change Under Rule 51.329(a)
Notification No. SN91083514
Issue Date: December 12, 2002