



January 2, 2003

RECEIVED

JAN - 2 2003

FEDERAL COMMUNICATIONS COMMISSION  
OFFICE OF THE SECRETARY

Ms. Marlene H. Dortch  
Secretary  
Office of the Secretary  
Federal Communications Commission  
445 12<sup>th</sup> Street, SW  
Washington, DC 20554

RE: **SBC Arneritech** Notice of Network Changes CC Docket No. 96-98, CFR 47, and  
Sections 51.325-51.335

Dear Ms. Dortch:

Attached is a **Revised Long-Term Network Disclosure** that **SBC Ameritech** submitted on **November 21, 2002**, associated with **Network Disclosure Nurnhers AIT20021120L.1 and AIT20021120L.2**. Revised disclosure is to change the information contained in section **Description of Type of Changes Planned**. As required, two copies of this material are being submitted herewith. In addition, as required, concurrent with this filing, a copy of this information is being submitted to the Chief, Wireline Competition Bureau, in paper form and in electronic form on a 3½-inch diskette.

Please call me if you have any questions regarding this matter.

Sincerely,

Attachments

CC: Chief, Wireline Competition Bureau

No. of Copies rec'd  
List ABOVE

24.2

Jonathan J. Boynton  
Associate Director -  
Federal Regulatory

SBC Telecommunications, Inc.  
1401 I Street, N.W., Suite 1100  
Washington, D.C. 20005  
Phone 202 526-8884  
Fax 202 408-4801



January 2, 2003

Mr. William Maher  
Chief  
Wireline Competition Bureau  
Federal Communications Commission  
445 12<sup>th</sup> Street, SW  
Washington, DC 20554

RE: **SBC Ameritech** Notice of Network Changes CC Docket No. 96-98: CFR 47, and  
Sections 51.325-51.335

Dear Mr. Maher:

Attached is a **Revised Long-Term Network Disclosure** that **SBC Ameritech** submitted on **November 21, 2002**, associated with **Network Disclosure Numbers AIT20021120L.1 and AIT20021120L.2**. Revised disclosure is to change the information contained in section **Description of Type of Changes Planned**. As required, two copies of this material are being submitted herewith, in paper form and in electronic form on a 3½-inch diskette. In addition, as required, concurrent with this filing, a copy of this information is being submitted to the Secretary, Office of the Secretary in paper form.

Please call me if you have any questions regarding this matter.

Sincerely,

A handwritten signature in black ink that reads 'Jonathan J. Boynton'. The signature is written in a cursive, flowing style.

Attachments

CC: Secretary, Office of the Secretary

**CERTIFICATION OF PUBLIC NOTICE(s) OF NETWORK  
CHANGE(s) UNDER RULE 51.329(a)**

On **December 30, 2002** the following Public Notice(s) of Network Change(s) have been made by **SBC Arneritech** pursuant to Code of Federal Regulations 47, Subsections 51.325 – 51.335.



Michael D. Jarmon  
Area Manager - Network Regulatory  
Telephone: (214) 858-1346                      Date: 12/30/2002

The Public Notice(s) can also be obtained on the Internet at:

[http://www.sbc.com/public\\_affairs/regulatory\\_documents/network\\_disclosures/0.5931,182.00.html](http://www.sbc.com/public_affairs/regulatory_documents/network_disclosures/0.5931,182.00.html)

**Title(s) of Network Notification(s):**

AIT20021120L.1

PUBLIC NOTICE of NETWORK CHANGE UNDER RULE 51.329(a)

Network Disclosure Number: AIT20021120L.1 Issue Date: 12/30/2002

Modification Date: 3<sup>RD</sup> Q/2003

Carrier's Name: Aineritech

Carrier's Address: 106 West Green Street, Montpelier, Indiana

Contact: Your Account Manager or Service Representative

Technical Issues  
Michael Jarmon  
Three Bell Plaza Rm 730.A2  
Dallas, Texas 75202  
(214) 858-1346  
mj4607@txrnail.sbc.com

Public can be obtained on the Internet at:

Notice: [http://www.sbc.com/public\\_affairs/regulatory\\_documents/network\\_disclosures/0,5931,182,00.html](http://www.sbc.com/public_affairs/regulatory_documents/network_disclosures/0,5931,182,00.html)

**For Internal Use Only**

Make/Buy Point: \_\_\_\_\_ Legal Review Date: \_\_\_\_\_

Need To Be Disclosed? (Please indicate by entering Yes, No or Under Review): Yes

Type of Filing: (Please indicate by entering Short-Term, Public Notice, Public Notice)

**For Network Change:** Network Access Services

**Contact Information:**

<i>Name</i>	<i>Telephone</i>	<i>E-Mail Address</i>
Project Sponsor:		
Brenda Bames	317-265-4635	bb1287@msg.ameritech.com
Project Manager:		
Larry Reynolds	317-252-5188	Joseph.L.Reynolds@msg.ameritech.com
Single Point/s of Contact (SPOC) (Person to be contacted in case of external inquiries):		
Bonita S. Jacobson	317-265-4262	BJ1714@SBC.COM
SME:		
Andrew Wilson	317-265-2831	AW7837@SBC.COM

**Network Change:**

Network Access Services
-------------------------

**Description of Type of Changes Planned:**

Ameritech announces the installation of a new Montpelier, Siemens Smart Remote switch, replacing the Montpelier, Nortel DMS-10, located in LATA 336, at 106 West Green Street . Montpelier, Indiana. The new CLLI, **MTPLIN01DS9** replaces MTPLIN01DS0. The following are the switch details:

**Cut Date: 3Q/2003**

New CLLI Code: MTPLIN01DS9

New Point Code: 250-040-043

Old CLLI Code: MTPLIN01DS0

Old Point Code: 250-040-035

NPA: 765 NXXs: 728

Carrier Project Codes:

**CLEC: AIIA-MOPPCLEC**

IXC: MOIXC

ILEC: MOLEC

Wireless: MOWIRE

BELL MESSAGE MOM

New Carrier MOC

Specials (DID): MOS

**Description of Reasonably Foreseeable Impact of the Planned Changes:**

SBC/Ameritech, Independent LECs, Wireless Service Providers, CLECs and Interexchange carriers will be affected for traffic originating and terminating to and from this end office. New trunks and/or trunk groups must be established between the carriers and the new office. Also, existing trunks/trunk groups between the former office and the carriers must be disconnected or downsized.

**CERTIFICATION OF PUBLIC NOTICE(s) OF NETWORK  
CHANGE(s) UNDER RULE 51.329(a)**

On **December 30, 2002** the following Public Notice(s) of Network Change(s) have been made by **SBC Arneritech** pursuant to Code of Federal Regulations 47, Subsections 51.325-- 51.335.



Michael D. Jarmon  
Area Manager - Network Regulatory  
Telephone: (214) 858-1346      Date: 12/30/2002

The Public Notice(s) can also be obtained on the Internet at:

[http://www.sbc.com/public\\_affairs/regulatory\\_documents/network\\_disclosures/0.5931.182,00.html](http://www.sbc.com/public_affairs/regulatory_documents/network_disclosures/0.5931.182,00.html)

**Title(s) of Network Notification(s):**

AIT20021 120L.2 Revision

PUBLIC NOTICE of NETWORK CHANGE UNDCR RULE 51.329(a)

Network Disclosure Number: AIT20021120L.2

Issue Date: 12/30/2002

Modification Date: 3<sup>RD</sup> Q/2003

Carrier's Name: Ameritech

Carrier's Address: 218 West Franklin Street Hartford City, Indiana.

Contact: Your Account Manager or Service Representative

Technical Issues  
Michael Jarmon  
Three Bell Plaza Rrn 730.A2  
Dallas, Texas 75202  
(214) 858-1346  
mj4607@txrmail.sbc.com

**Public can be obtained on the Internet at:**

**Notice:** [http://www.sbc.com/public\\_affairs/regulatory\\_documents/network\\_disclosures/0,5931,182,00.html](http://www.sbc.com/public_affairs/regulatory_documents/network_disclosures/0,5931,182,00.html)

**Network Change:**

Network Access Services

**Description of Type of Changes Planned:**

Ameritech announces revisions to the Installation of a new Hartford City, Siemens Smart Remote switch, replacing the Hartford City, Nortel DMS-10, located in LATA 336, at 218 West Franklin Street Hartford City, Indiana. The new CLLI, **HRCYIN01DS9** replaces HRCYIN01DS0. The following are the switch details:

**Cut Date: 3Q/2003**

New CLLI Code: HRCYIN01DS9

New Point Code: 250-040-042

Old CLLI Code: HRCYIN01DS0

Old Point Code: 250-050-030

NPA: 765 NXXs: 331, 348

Carrier Project Codes:

CLEC: **AIIA-HAPPCLEC**

IXC: HAIXC

ILEC: HALEC

Wireless: HAWIRE

BELL MESSAGE: HAM

New Carrier: HAC

Specials (DID) HAS

**Description of Reasonably Foreseeable Impact of the Planned Changes:**

SBC/Ameritech, Independent LECs, Wireless Service Providers, CLECs and Interexchange carriers will be affected for traffic originating and terminating to and from this end office. New trunks and/or trunk groups must be established between the carriers and the new office. Also, existing trunks/trunk groups between the former office and the carriers must be disconnected or downsized.