



1250 Eye Street, N.W., Suite 901
Washington, D.C. 20005

18 March 2011

WT Docket No. 06-136

Office of the Secretary
Federal Communications Commission
The Portals
445 Twelfth Street, S.W.
12th Street Lobby, TW-A325
Washington, DC 20554

RE: Post-Transition Notification - NSAC, LLC
Transition of the 2500-2690 MHz Band for BRS and EBS
Transition Area: BTA Number 488: San Juan, PR

Dear Ms. Dortch:

NSAC, LLC, a wholly-owned subsidiary of Clearwire Corporation (together "Clearwire"), and the designated Proponent for the market, hereby notifies the Commission, pursuant to Section 27.1235 of its Rules, that it has timely completed the Transition for BTA Number 488: San Juan, PR.

As required by Section 21.1235, attached hereto are the following:

- **Exhibit 1** which contains a list of the licensees that have transitioned to the new band plan;
and
- **Exhibit 2** listing each station in the MBS including
 - the station coordinates,
 - antenna make and model,
 - the horizontal and vertical pattern of the antenna,
 - the EIRP of the main lobe,
 - antenna orientation,
 - height of the antenna center of radiation,
 - transmitter output power, and
 - the line and combiner losses.

As required by Section Section 27.1235(c), a copy of the subject Post-Transition Notification is being served on all parties to the transition of this market as listed in **Exhibit 1**.

If you have any questions regarding this matter please contact Brandon Bullis, Director of Spectrum Development, at (202) 351-5021 or the undersigned at (202) 330-4011.

Sincerely,



Nadja Sodos-Wallace

cc: Joel Taubenblatt, Chief, Broadband Division, WTB
John Schauble, Deputy Chief, Broadband Division, WTB
Consuela Kearney, Industry Analyst, Broadband Division, WTB

Exhibit 1
List of Facilities That Have Been Transitioned

The authorizations listed below have been transitioned by Clearwire to the frequencies assigned to them under §27.5(i)(2). In the case of authorizations for BRS channels 1 and/or 2 (identified by "M1" and "M2"), the Proponent has no responsibility for transitioning facilities operating on these channels. The post-transition frequency assignments for BRS channels 1 and 2 are being reserved for future accommodation of services licensed for these channels.

BTA #488: San Juan, PR

WHT654, Sala Business Corporation	Channels: E1E2E3E4
WHT655, NSAC, LLC	Channels: F1F2F3F4
WLX315, Caribbean University	Channels: C1C2C3C4
WLX321, Catholic Archdiocese Of San Juan	Channels: A1A2A3A4
WLX322, Puerto Rico Medical Association	Channels: D1D2D3D4
WLX323, HITN - Puerto Rico, LLC	Channels: B1B2B3B4
WLX662, Sistema Universitario Ana G. Mendez, Inc.	Channels: C1C2C3C4
WLX664, Sistema Universitario Ana G. Mendez, Inc.	Channels: G1G2G3G4
WNC694, Sistema Universitario Ana G. Mendez, Inc.	Channels: G1G2G3G4
WNC698, Hispanic Information and Telecommunications Network, Inc.	Channels: B1B2B3B4
WNC703, Sistema Universitario Ana G. Mendez, Inc.	Channels: C1C2C3C4
WNC706, Hispanic Information and Telecommunications Network, Inc.	Channels: D1D2D3D4
WNC864, Sistema Universitario Ana G. Mendez, Inc.	Channels: G1G2G3G4
WNTB423, NSAC, LLC	Channels: H2

Exhibit 1
List of Facilities That Have Been Transitioned (continued)

WNTB467, NSAC, LLC Channels: H3

WNTF632, NSAC, LLC Channels: H1

WQLW507, Clearwire Spectrum Holdings III, LLC Channels:
BRS1BRS2E1E2E3E4F1F2F3
F4H1H2H3

Exhibit 2

List of Required Technical Parameters for Stations In The MBS

Page 1 of 3

Clearwire

BTA #488: San Juan, PR

WHT654, Sala Business Corporation

Post-Transition MBS Parameters:

MBS Channel E4: 2608.0 - 2614.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WHT655, NSAC, LLC

Post-Transition MBS Parameters:

MBS Channel F4: 2602.0 - 2608.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WLX315, Caribbean University

Post-Transition MBS Parameters:

MBS Channel C4: 2584.0 - 2590.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WLX321, Catholic Archdiocese Of San Juan

Post-Transition MBS Parameters:

MBS Channel A4: 2572.0 - 2578.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WLX322, Puerto Rico Medical Association

Post-Transition MBS Parameters:

MBS Channel D4: 2590.0 - 2596.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WLX323, HITN - Puerto Rico, LLC

Post-Transition MBS Parameters:

MBS Channel B4: 2578.0 - 2584.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

Exhibit 2

List of Required Technical Parameters for Stations In The MBS

Page 2 of 3

Clearwire

BTA #488: San Juan, PR

WLX662, Sistema Universitario Ana G. Mendez, Inc.

Post-Transition MBS Parameters:

MBS Channel C4: 2584.0 - 2590.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WLX664, Sistema Universitario Ana G. Mendez, Inc.

Post-Transition MBS Parameters:

MBS Channel G4: 2596.0 - 2602.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WNC694, Sistema Universitario Ana G. Mendez, Inc.

Post-Transition MBS Parameters:

MBS Channel G4: 2596.0 - 2602.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WNC698, Hispanic Information and Telecommunications Network, Inc.

Post-Transition MBS Parameters:

MBS Channel B4: 2578.0 - 2584.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WNC703, Sistema Universitario Ana G. Mendez, Inc.

Post-Transition MBS Parameters:

MBS Channel C4: 2584.0 - 2590.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WNC706, Hispanic Information and Telecommunications Network, Inc.

Post-Transition MBS Parameters:

MBS Channel D4: 2590.0 - 2596.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

Exhibit 2

List of Required Technical Parameters for Stations In The MBS

Page 3 of 3

Clearwire

BTA #488: San Juan, PR

WNC864, Sistema Universitario Ana G. Mendez, Inc.

Post-Transition MBS Parameters:

MBS Channel G4: 2596.0 - 2602.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

WNTB423, NSAC, LLC

Post-Transition MBS Parameters:

This license does not include MBS channels.

WNTB467, NSAC, LLC

Post-Transition MBS Parameters:

This license does not include MBS channels.

WNTF632, NSAC, LLC

Post-Transition MBS Parameters:

This license does not include MBS channels.

WQLW507, Clearwire Spectrum Holdings III, LLC

Post-Transition MBS Parameters:


MBS Channel E4: 2608.0 - 2614.0 MHz

MBS Channel F4: 2602.0 - 2608.0 MHz

This licensee is not currently operating in the Mid-Band Segment.

Certification

Pursuant to Section 27.1235 of the Commission's Rules, NSAC, LLC certifies that it has completed the transition of the San Juan, PR Basic Trading Area, BTA #488.



Nadja Sodos-Wallace

Regulatory Counsel and Assistant Secretary